



Testing Operation of the Hornet 2600 Livestock Prod

1. Check that the Prod is assembled correctly and that all connections are secure.
2. Press the Power Button until it clicks
3. Check Battery meter is showing 3 green bars and 1 red bar
4. Touch both prong tip points to a metal surface, and press the trigger button. A visible spark on contact should occur.

Symptom	Possible Cause	Possible Fix
Battery Indicator has no lights, unit has no power.	Unit is not charged or turned on	Press power button down until it clicks. Battery indicator lights should turn on. If only one red light turns on and no green lights unit needs charged.
No Shock	Metal prongs bent or not making contact. Possible bad shaft or bad connection.	If using a NON - HerculesAG shaft be sure that the copper connectors on the shaft are opened up and not pushed down. If you are using a used shaft from another brand you will need to open up the copper connectors on the bottom. If using a HerculesAG shaft, inspect connection prongs at handle and collar nut. Turn power on, look for battery indicator of 3 green lights, 1 red light, touch both prong tip points to a metal surface or hold a screwdriver to where the metal end is touching both tips. Press the trigger button. If no arc, then shaft possibly needs to be replaced. We only guarantee functionality of our HerculesAG shafts.